



WEEKLY SUMMARY REPORT

PROJECT NO.:	2476.0001Y002	WEEKLY REPORTING PERIOD: Monday July 24, 2017 through Sunday July 30, 2017
PROJECT:	CFAC Phase I Site Characterization	
LOCATION:	Near Columbia Falls, Montana	

SUMMARY OF WORK COMPLETED

- Performed additional pneumatic slug tests of 2-inch monitoring wells at the following 3 locations in accordance with Phase I SAP Modification #11: CFMW-003a, CFMW-032a, and CFMW-056a.
- Performed additional mechanical slug tests of 2-inch monitoring wells at the following 3 locations in accordance with Phase I SAP Modification #11: CFMW-008a, CFMW-053a, and CFMW-057a.
- Continued analysis of slug test data to determine hydraulic conductivity values in accordance with Phase I SAP Modification #11.

SUMMARY OF WORK PLANNED FOR NEXT WEEK / ANTICIPATED SCHEDULE CHANGES

- Planned
 - Continue analyzing pneumatic and mechanical slug test data
 - Begin Asbestos Landfill surface soil sampling with support of Hydrometrics in accordance with Phase I SAP Modification #10.
- Modifications
 - No modifications to schedule or deviations from Work Plan or Sampling and Analysis Plan.

HEALTH AND SAFETY NOTES

- Roux Associates personnel discussed hazards and preventative measures associated with heat stress.

OTHER NOTES

- No other notes.

Prepared By Mike Ritorto Of Roux Associates, Inc.